

1.1.1.5 Accessories for Photodiode Sensors


Fiberoptic Adapters and Other Accessories

PD300 with F.O. Adapter Mounted



Accessories and Fiberoptic Adapters for PD300 series

| Accessory | Description | Part number | | | |
|----------------------------------|--|-------------|---------|-------------------|----------|
| PD300-CDRH-7mm | Ø7mm aperture adapter for CDRH measurements for PD300 | 7Z02418 | | | |
| PD300-CDRH-3.5mm | Ø3.5mm aperture adapter for CDRH measurements for PD300 | 7Z08336 | | | |
| Fiber Adapters for Sensor Series | Adapters for mounting fibers to PD300 sensors as shown below | SC type | ST type | FC, FC / APC type | SMA type |
| PD300 Series | | 7Z08221 | 7Z02210 | 7Z02213 | 7Z02212 |



Accessories and Fiberoptic Adapters for PD300R series, PD300-IRG, 3A-IS, IS-1-2W and FPD series

SC fiber adapter ST fiber adapter FC fiber adapter SMA fiber adapter



| Accessory | Description | Part number | | | |
|----------------------------------|---|-------------|---------|-------------------|----------|
| PD300R-CDRH-7mm | Ø7mm aperture adapter for CDRH measurements for PD300R | 7Z08347 | | | |
| Fiber Adapters for Sensor Series | Fiber adapter mounting bracket (1 bracket fits all fiber adapters) | SC type | ST type | FC, FC / APC type | SMA type |
| FPD Series | 1G02259 - not needed except for FPS-1 | 7Z08227 | 7Z08226 | 7Z08229 | 1G01236A |
| PD300R Series | 1G02259 | 7Z08227 | 7Z08226 | 7Z08229 | 1G01236A |
| 3A-IS / 3A-IS-IRG | 7Z08213 | 7Z08227 | 7Z08226 | 7Z08229 | 1G01236A |
| IS-1-2W | 7Z08331 | 7Z08227 | 7Z08226 | 7Z08229 | 1G01236A |
| PD300-IRG | not needed | | | 7Z08216 | 7Z08222 |
| Female SM1 to SM1 Adapter | For mounting PD300R series, PD300RM-UV & PD300RM-8W and FPS-1 sensors to SM1 optical components and systems | | | | 1G02260 |

