

NanoScan™ Quality of Life Improvements

Dell Olsen, Customer Service Manager, Ophir

Ophir has been blessed to have customers who have been patient and helped us find and fix some difficulties with the NanoScan™ software. We are pleased to announce that due to the feedback and help of our customers, we have significantly improved the NanoScan software.

Some of the key features include:

- All NanoScans that have been made or upgraded to the NanoScan version 2 software will now run on the same version of software. The older 26-pin versions of the NanoScan hardware used to require their own version of the software (2.1 SR1), which is no longer the case.
- The new software will make it easy to upgrade to a newer firmware version for the USB versions of the NanoScan hardware without sending the unit to our facility to be updated.
- We have improved some long runtime errors which have been reported when performing long term testing and monitoring of lasers, especially through automation clients.

To see more information please visit the [Software Download](#) page and view the ReadMe file.

Photon Software

NanoScan Software

Product	32-bit	64-bit	Version	Release Date	Size (MB)	
NanoScan v2	Yes	Yes	2.5	12/20/2017	18.5	Readme
NanoModeScan	Yes	Yes	2.52	11/02/2013	8.8	Readme

! Note

- As of version 2.5 all types of NanoScan heads, including legacy 26 pin interface cable heads are compatible with the software. Users of version 2.1SR1 may upgrade to version 2.5 or higher.
- NanoScan v2 software is a paid version upgrade from NanoScan v1.47. If you wish to upgrade please contact your local Spiricon Sales representative by calling (800) 383-0814