
1.1.1.5 Accessories for Photodiode Sensors

Fiberoptic Adapters and Other Accessories


Accessories and Fiberoptic Adapters for PD300 series


Accessory	Description	Part number			
PD300-CDRH-7mm	Ø7mm aperture adapter for CDRH measurements for PD300	7Z02418			
PD300-CDRH-3.5mm	Ø3.5mm aperture adapter for CDRH measurements for PD300	7Z08336			
Fiber Adapters for Sensor Series	Adapters for mounting fibers to PD300 sensors as shown below	SC type	ST type	FC, FC / APC type	SMA type
PD300 Series		7Z08221	7Z02210	7Z02213	7Z02212






PD300-FO-SMA







Accessory	Description	Part number			
PD300R-CDRH-7mm	Ø7mm aperture adapter for CDRH measurements for PD300R	7Z08347			
Fiber Adapters for Sensor Series	Fiber adapter mounting bracket (1 bracket fits all fiber adapters)	SC type	ST type	FC, FC / APC type	SMA type
FPD Series	1G02259 - not needed except for FPS-1	7Z08227	7Z08226	7Z08229	1G01236A
PD300R Series	1G02259	7Z08227	7Z08226	7Z08229	1G01236A
3A-IS / 3A-IS-IRG	7Z08213	7Z08227	7Z08226	7Z08229	1G01236A
IS-1-2W	7Z08331	7Z08227	7Z08226	7Z08229	1G01236A
PD300-IRG	not needed			7Z08216	7Z08222
Female SM1 to SM1 Adapter	For mounting PD300R ser and FPS-1 sensors to SM	1G02260			

