

1.2.4.1 Accessories for Pyroelectric Sensors - Continued


Damage Threshold Test Plates



Nova PE-C Adapter



PE-C to PE Size Adapter



Negative Polarity Power Supply/Charger



Accessory	Description	Part number		
		Metallic type	BF type	BB type
Damage Threshold Test Plates	Test plates with same absorber coating as the sensor. For testing that laser beam is not above damage threshold	7E06031A	7E06031D	7E06031C
	Dimensions	26x26x1mm	76x26x1mm	76x26x1mm
Nova PE-C Adapter	The adapter plugs between the Nova D15 socket and the smart plug of the PE-C sensor to allow the Nova to operate with PE-C series sensors. See PE-C spec sheet for details.	7Z08272		
PE-C to PE Size Adapter	The newer PE-C series sensors have a Ø62mm diameter. The older PE series sensors have a Ø85mm diameter. This adapter allows using the PE-C type sensors in jigs and setups that were originally designed for PE sensors.	7Z08273		
N Polarity Power Supply/Charger AC/DC 12V 2A N-2.1x5.5	For FPE80BF-DIF-C sensor (1 unit supplied with the sensor)	7E05029		